

#844: 2011 Toro Workman MDX Utility Vehicle

VIN #311000211

869 Hours

Parks Department



Known Issues:

- * Bad head gasket

THIS IS AN "AS IS" SALE

The City of Ashland makes no representations, warranties or guarantees, either express or implied, about the condition, operability or safety of this equipment. Bidders have sole responsibility for evaluating the condition and value of this equipment.

The City's interest in this equipment and any responsibility whatsoever for it will be extinguished upon transfer of title to the successful bidder. The City will not thereafter refund any portion of the purchase price or undertake any further actions with respect to this equipment.

The buyer must agree in writing to hold the City of Ashland, its officers, employees and agents harmless from any claim arising from the maintenance, operation or resale of this equipment.

As a courtesy, the City has listed above some of the problems it has so far identified with this equipment. This list is not based on a comprehensive or detailed inspection, is not based on systematic reviews by past users or mechanics, and is not therefore exhaustive. **DO NOT RELY EXCLUSIVELY ON THIS LIST TO ASSESS THE CONDITION AND VALUE OF THIS EQUIPMENT.** Maintenance records on this equipment are available for review.